

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D1049257	<b>(X3) Date Survey Completed</b>  05/03/2023
<b>Name of Provider or Supplier</b>  Interventional Spine Specialists Of Florida Llc	<b>Street Address, City, State</b>  7171 N University Dr Ste 300, Tamarac, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A recertification survey conducted on 05/03/2023 found the ANESTHESIA PAIN CARE CONSULTANTS LLC clinical laboratory not in compliance with 42 CFR Part 493, Requirements for Laboratories.
<b>D2009</b>	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>The individual testing or examining the samples and the laboratory director must attest to the routine integration of the samples into the patient workload using the laboratory's routine methods.</p> <p>This STANDARD is not met as evidenced by: Based on record review and staff interview, the laboratory director (LD) failed to sign two out of six events reviewed for Urine Toxicology specialty. Findings included: - Review of College of American Pathologists (CAP) Attestation statement noted "The laboratory director or designee and the testing personnel must sign on the result form. " -Review of CAP proficiency testing (PT) records for years 2021 (second and third event), 2022 (first, second and third event) and 2023 (first event) revealed that the LD failed to sign attestation for the 1st event of 2022 and 2023 in the specialty of Urine Toxicology. During an interview on 05/03/2023 at 12:25 PM, the Technical Supervisor confirmed that the LD failed to sign the attestation for the events of reference.</p>