

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1085556	(X3) Date Survey Completed 09/04/2018
Name of Provider or Supplier Firstpath Laboratory Services Llc	Street Address, City, State 3141 W Mcnab Rd, Pompano Beach, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with Testing Person # A (TPA), the laboratory failed to verify the accuracy of frozen sections slides twice annually for 2 out of 2 years. Findings include: Review of verification accuracy records on 9/4/2018 showed that for year 2017 only one performed and for year 2018 from January to August no accuracy evaluation done During and interview with the TPA at 11:00 a.m. on 09/04 /2018 confirmed that there was no documentation to indicate that verification accuracy done twice during 2017 and for 2018 no accuracy verification performed from January to August.</p>