

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D2020895	(X3) Date Survey Completed 05/15/2018
Name of Provider or Supplier Brandon Dermatology Pa	Street Address, City, State 406 W Bloomingdale Ave, Brandon, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6094	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(5)</p> <p>The laboratory director must ensure that the quality assessment programs are established and maintained to assure the quality of laboratory services provided and to identify failures in quality as they occur.</p> <p>This STANDARD is not met as evidenced by: Based on procedure manual and laboratory logs record review and interview with the Practice Administrator, the Laboratory Director failed to have a Quality Assurance procedure. Findings included: During the procedure manual record review, it was discovered the procedure manual did not include a Quality Assurance procedure. During the record review of the laboratory's logs, it was found that documentation of quality assurance activities was missing from the laboratory's records. During an interview on 05/15/2018 at 1:00 p.m, the Practice Administrator confirmed that the laboratory did not have a Quality Assurance procedure.</p>