

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 11D0710009	(X3) Date Survey Completed 03/11/2026
Name of Provider or Supplier Summit Medical Associates Pc	Street Address, City, State 1874 Piedmont Rd Ste 500-E, Atlanta, GA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A Clinical Laboratory Improvement Amendments (CLIA) Recertification Survey was completed on March 11, 2026. The laboratory was not in compliance with applicable CLIA requirements found at 42 CFR 493.1 through 42 CFR 493.1780. The following deficiencies were cited:
D2009	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>(b)(1) The individual testing or examining the samples and the laboratory director must attest to the routine integration of the samples into the patient workload using the laboratory's routine methods.</p> <p>This STANDARD is not met as evidenced by: A review of the 2024 - 2025 AAB Medical Laboratory Proficiency Records confirmed that the laboratory failed to attest to the routine integration of the proficiency samples into the patient workload using the laboratory's routine methods. THE FINDINGS INCLUDE: 1. A review of 2024 - 2025 AAB Medical Laboratory Proficiency Records confirmed that five (5) of six (6) Proficiency Testing Attestation Statements were unsigned. 2. A 2024 - 2025 AAB Medical Laboratory Proficiency Records confirmed that one (1) of six (6) Proficiency Testing Attestation Statements was signed by unqualified personnel. 3. An exit interview, with the Laboratory Manager and Testing Personnel, on March 11, 2026, at 1:00pm confirmed that the Laboratory Director failed to attest to the routine integration of the samples into the patient workload using the laboratory's routine methods.</p>