

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 11D0724969	(X3) Date Survey Completed 08/04/2026
Name of Provider or Supplier Mcintosh Clinic Pc	Street Address, City, State 119 West Hill St, Thomasville, GA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A Clinical Laboratory Improvement Amendments (CLIA) recertification survey was completed on August 04, 2026. The laboratory was not in compliance with applicable CLIA requirements found at 42 CFR 493.1 through 42 CFR 493.1780. The following deficiencies were cited:
D6128	TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9) (b)(9) Thereafter, evaluations must be performed at least annually unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individuals performance must be reevaluated to include the use of the new test methodology or instrumentation. This STANDARD is not met as evidenced by: Based on review of testing personnel documents and an interview with the laboratory director, the technical supervisor failed to perform annual competency on all testing personnel. Findings 1. Review of testing personnel competency assessments revealed the technical supervisor failed to perform annual competency on (1 of 4) testing personnel, #4 (CMS 209) for the years 2025 and 2026 to date. 2. Interview with the technical supervisor (CMS 209) confirmed the lack of competency evaluation documents for the above mentioned testing personnel. Confirmation was at 11:38 am on August 4, 2026 in his office.