

| | | |
|--|--|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 11D2112585 | (X3) Date Survey Completed 09/10/2025 |
| Name of Provider or Supplier Biolife Plasma Services, Lp | Street Address, City, State 505 Shire Parkway, Building D, Social Circle, GA | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|---|
| D0000 | A Clinical Laboratory Improvement Amendments (CLIA) recertification survey was completed on Sept. 10, 2025. The laboratory was not in compliance with applicable CLIA requirements found at 42 CFR 493.1 through 42 CFR 493.1780. The following deficiencies were cited: |
| D6053 | <p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>(b)(9) Evaluating and documenting the performance of individuals responsible for moderate complexity testing at least semiannually during the first year the individual tests patient specimens.</p> <p>This STANDARD is not met as evidenced by: Based on review of testing personnel (TP) training/competency documents and an interview with the lab director (LD), the technical consultant failed to perform semiannual competency on all testing personnel. Findings: 1. Review of the TP training/competency documents reveals TP#1 (CMS 209 page 1 of 6) had initial competency evaluated 2/5/24 and annual competency evaluated on 2/28/25 but no semiannual competency evaluation performed. 2. Review of the TP training /competency documents reveals TP#2 (CMS 209) had initial competency evaluated 1 /29/25 but no semiannual competency evaluation performed to date. 3. Interview with the LD in the conference room on 9/10/25 at 11:10 am confirmed the lack of semi annual competency on the aforementioned TP.</p> |