

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 13D2099992	(X3) Date Survey Completed 03/26/2026
Name of Provider or Supplier Sterling Urgent Care	Street Address, City, State 1404 Pomerelle Ste A1, Burley, ID	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	Based on an offsite paper revisit the laboratory was found to be in compliance with CLIA regulations (42 CFR Part 493 effective April 24, 2003.), all previous deficiencies found were corrected.
D5209	<p>PERSONNEL COMPETENCY ASSESSMENT POLICIES CFR(s): 493.1235</p> <p>As specified in the personnel requirements in subpart M, the laboratory must establish and follow written policies and procedures to assess employee and, if applicable, consultant competency.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the submitted Centers for Medicare and Medicaid Services (CMS) 209 personnel form, laboratory policies, training and competency assessment records and an interview with the laboratory consultant on 3/26/2026, the laboratory failed to establish and follow written policies and procedures to assess testing personnel training and competency in 2025. The findings include: 1. The CMS 209 identified six (6) testing personnel performing moderate complexity testing. 2. A review laboratory policies identified the laboratory failed to have a policy for performing training and competency assessments. 3. A review of training and competency assessment records identified one (1) of four (4) testing personnel that failed to have initial training documented. Testing personnel four (4) had a start day of 12/11/2025 and failed to have documentation of initial training prior to performing patient testing. 4. An interview with the laboratory consultant on 3/26/2026 at 12:50 pm confirmed the above findings. 5. The laboratory reports performing 1200 tests annually.</p>