

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  13D2215112	<b>(X3) Date Survey Completed</b>  09/03/2021
<b>Name of Provider or Supplier</b>  Pro-Testing Solutions Llc	<b>Street Address, City, State</b>  296 W Sunset Ave Ste 10, Coeur D'Alene, ID	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D2003</b>	<p>ENROLLMENT CFR(s): 493.801(a)(2)(ii)</p> <p>For those tests performed by the laboratory that are not included in subpart I of this part, a laboratory must establish and maintain the accuracy of its testing procedures, in accordance with 493.1236(c)(1)</p> <p>This STANDARD is not met as evidenced by: Based on a review of proficiency testing (PT) from the College of American Pathologists (CAP) and an interview with the General Supervisor (GS) on 9/3/2021, the laboratory failed to enroll in proficiency testing to verify the accuracy of testing for the SARS-CoV-2-qRT-PCR assay in accordance with 493.1236(c)(1). The findings include: 1. A review of proficiency testing records from CAP identified that the laboratory failed to verify the accuracy of testing for the SARS-CoV-2-qRT-PCR saliva assay for 2021. 2. An interview with the GS on 9/3/2021 at 12:54 pm confirmed that the laboratory failed to verify the accuracy of testing for the SARS-CoV-2-qRT-PCR saliva assay for 2021. 3. The laboratory reports performing 400 SARS-CoV-2-qRT-PCR saliva tests annually.</p>