

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 16D2073760	(X3) Date Survey Completed 03/08/2022
Name of Provider or Supplier The Iowa Clinic - Indianola	Street Address, City, State 1504 North 1st Street, Indianola, IA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6054	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: Based on review of personnel records and confirmed by the Clinical Laboratory Manager at approximately 11:45 am on 03/08/2022, the technical consultant failed to assess and document the competency of individuals performing moderate complexity testing (complete blood count) at least annually for three out of three testing personnel (personnel identifiers #2- #4) in 2020 and 2021.</p>