

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 17D0985294	(X3) Date Survey Completed 01/25/2022
Name of Provider or Supplier Labcorp Kansas, Inc - Main Lab	Street Address, City, State 2916 E Central Ave, Wichita, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5543	<p>HEMATOLOGY CFR(s): 493.1269(a)(d)</p> <p>(a) For manual cell counts performed using a hemocytometer-- (a)(1) One control material must be tested each 8 hours of operation; and (a)(2) Patient specimens and control materials must be tested in duplicate. (d) The laboratory must document all control procedures performed, as specified in this section.</p> <p>This STANDARD is not met as evidenced by: Based on review of manual cell counts test logs and interview, the laboratory failed to perform one control level in duplicate and failed to perform patient testing in duplicate for manual cell counts using a hemocytometer on one of one patients January 6, 2022. Findings: 1. Review of manual cell count test logs showed patient testing was not being performed in duplicate on one of one patients on January 6, 2022 at time of survey. 2. Quality Control (QC) records for manual cell counts were requested, there was no QC performed in duplicate on January 6, 2022. 3. GS #1 stated the QC performed on manual cell counts was a comparison of the automated hematology analyzer result to the manual result of one of one patients. 4. Interview with GS #1 at 2:15pm on January 25, 2022 confirmed, the laboratory failed to perform one control level in duplicate and failed to perform patient testing in duplicate for one of one patients on January 6, 2022 for manual cell counts using a hemocytometer at time of survey.</p>