

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 17D2229578	(X3) Date Survey Completed 10/18/2023
Name of Provider or Supplier Kansas City Vascular Institute, P-Llc	Street Address, City, State 5320 College Blvd, Overland Park, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2007	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>The samples must be examined or tested with the laboratory's regular patient workload by personnel who routinely perform the testing in the laboratory, using the laboratory's routine methods</p> <p>This STANDARD is not met as evidenced by: Based on the review of proficiency testing (PT) attestation pages, CMS-209 personnel report and interview, the laboratory failed to include personnel who routinely perform the regular patient testing in the testing of proficiency samples. Findings: 1 Review of American Proficiency Institute (API) PT attestation pages from 4/1/22 to 10/10/23 revealed all testing had been performed by testing personnel (TP) #1 for eight of eight testing events. 2. Review of the CMS 209 reveals that TP #1 is also technical consultant (TC) #2. There was a total of eight testing personnel on the CMS-209. Only one of eight TP performed PT sample testing. 3. Interview with TC #2 on 10/18/23 at 10:40 a.m. confirmed, the laboratory failed to include personnel who routinely perform the regular patient testing in the testing of proficiency samples.</p>