

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  19D0460740	<b>(X3) Date Survey Completed</b>  09/27/2023
<b>Name of Provider or Supplier</b>  Ronald J Daigle, Md, Apmc	<b>Street Address, City, State</b>  155 Hospital Drive Suite 404, Lafayette, LA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A Recertification Survey was performed on September 27, 2023 at Ronald J. Daigle, M.D., CLIA ID # 19D0460740. The laboratory was found in compliance with 42 CFR 493 Requirements for Laboratories; however, standard level deficiencies were cited.
<b>D5217</b>	<p><b>EVALUATION OF PROFICIENCY TESTING PERFORMANCE</b> CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on review of twice annual verification records and the laboratory's policy and procedure manual, as well as interview with personnel, the laboratory failed to verify the accuracy of the performance of Histopathology testing at least twice annually. Findings: 1. Review of the laboratory's test menu revealed the laboratory reads Histopathology slides. 2. Review of the laboratory's policies and procedures revealed "Twice a year, 2 pathology specimens that have been interpreted by Dr. Daigle will be verified by a pathologist or a board certified dermatologist who is proficient in dermatopathology." 3. Review of the laboratory's twice annual verification documents revealed the laboratory did not have documentation of the verification of the accuracy of Histopathology testing for 2022 and the first half of 2023. 4. In interview on September 27, 2023 at 1:29 p.m., the Laboratory Director confirmed a twice annual performance verification was not performed in 2022 and the first half of 2023.</p>
<b>D6087</b>	<p><b>LABORATORY DIRECTOR RESPONSIBILITIES</b> CFR(s): 493.1445(e)(3)(iii)</p> <p>The laboratory director must ensure that laboratory personnel are performing the test methods as required for accurate and reliable results.</p>

This STANDARD is not met as evidenced by:  
Based on record review and interview with personnel, the Laboratory Director failed to ensure laboratory personnel were performing the test methods as required for accurate and reliable results. Refer to D5217.