

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  19D1032343	<b>(X3) Date Survey Completed</b>  04/30/2025
<b>Name of Provider or Supplier</b>  Tri-Parish Pediatrics	<b>Street Address, City, State</b>  4937 Hearst Street Suite 2a, Metairie, LA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	A Recertification survey was performed at Tri-Parish Pediatrics, CLIA ID 19D1032343, on April 30, 2025. The laboratory was found in compliance with 42 CFR 493 Requirements for Laboratories; however, standard level deficiencies were cited.
<b>D5417</b>	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(d)</p> <p>(d) Reagents, solutions, culture media, control materials, calibration materials, and other supplies must not be used when they have exceeded their expiration date, have deteriorated, or are of substandard quality.</p> <p>This STANDARD is not met as evidenced by: Based on observation by surveyor, review of expiration check logs, and interview with personnel, the laboratory failed to ensure one (1) of three (3) Uricult test kits had not exceeded its expiration date. Findings: 1. Observation by surveyor during the laboratory tour on April 30, 2025 revealed the following expired Uricult test kit: Aidian CLED EMB Uricult, lot 1922282, expiration date: 2025-03-21, Quantity: five (5) vials 2. Review of the laboratory's "Expired Product Check Log" revealed the laboratory performed checks for expired items on the following dates without identification of the expired test kit: March 22, 2025 March 29, 2025 April 5, 2025 April 12, 2025 April 19, 2025 April 26, 2025 3. In interview on April 30, 2025 at 1:18 pm, Testing Personnel 1 confirmed the identified Uricult test kit was expired.</p>
<b>D6014</b>	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(3)(iii)</p> <p>(e)(3)(iii) Laboratory personnel are performing the test methods as required for accurate and reliable results;</p>

This STANDARD is not met as evidenced by:  
Based on observation by surveyor, record review, and interview with personnel, the Laboratory Director failed to ensure the laboratory personnel performed test methods as required. Refer to D5417.