

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 21D0219030	(X3) Date Survey Completed 01/27/2025
Name of Provider or Supplier Hillcrest Clinic Inc	Street Address, City, State 5602 Baltimore National Pike 600, Baltimore, MD	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2007	<p>TESTING OF PROFICIENCY TESTING SAMPLES CFR(s): 493.801(b)(1)</p> <p>The samples must be examined or tested with the laboratory's regular patient workload by personnel who routinely perform the testing in the laboratory, using the laboratory's routine methods</p> <p>This STANDARD is not met as evidenced by: Based on review of proficiency testing records for Rh (D) testing and interview with Testing Person A, the laboratory did not rotate proficiency testing among all staff performing the Rh (D) testing. Findings: 1. All three proficiency testing events for Rh (D) testing performed in the year 2024 were performed by Testing Person A, even though there were other staff members who also performed Rh(D) testing on patient samples. 2. During interview on 1/27/25, Testing Person A confirmed that the proficiency testing was not rotated among other staff members for the entire year of 2024.</p>