

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 21D0219529	(X3) Date Survey Completed 04/17/2019
Name of Provider or Supplier Upper Chesapeake Hematology/Oncology Svcs Llc	Street Address, City, State 650 Mchenry St Suite 3100, Aberdeen, MD	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6120	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on review of the competency reviews for the high complexity testing personnel and interview with the point of care (POC) coordinator, the technical supervisor did not ensure that the high complexity testing personnel maintained their competency by performing the hematology slide review twice a year as required. Findings: 1. Review of the Summary sheet dated "01-01-2018 - 01-01-2019" for "Upper Chesapeake Health" showed that 3 of the 4 high complexity testing personnel had performed only one of the two required competency reviews for 2018. 2. During the survey on 04/17 /19 at POC coordinator confirmed that 3 of the 4 high complexity testing personnel had performed only one of the two required competency reviews for 2018. both</p>