

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D2077422	(X3) Date Survey Completed 11/14/2018
Name of Provider or Supplier Beaumont Multi Specialty Services	Street Address, City, State 27900 Grand River, Ste #230, Farmington Hills, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: . Based on record review and interview, the laboratory failed to at least twice annually verify the accuracy of 1) the histopathology Mohs' tissue slide examination for four (2nd 2016, 1st and 2nd 2017, and 1st 2018) of four twice annual evaluation events and 2) the twice a year Michigan Dermatological Society examination for four (fall 2016, spring and fall 2017, and spring 2018) of five seasonal exams. Findings include: 1. On November 14, 2018 at 9:52 AM, record review of the "Mohs Case Quality Assurance Form" revealed the laboratory did not perform at least twice a year verification of accuracy for the Mohs' specimens processed on-site as follows: a. 2016 - 2nd event b. 2017 - 1st and 2nd events c. 2018 - 1st event 2. On November 14, 2018 at 10:30 AM, lack of records revealed the laboratory director did not complete and document the twice a year (spring/fall) Michigan Dermatological Society examinations as follows: a. 2016 - no fall b. 2017 - no spring or fall c. 2018 - no spring 3. On November 14, 2018 at 9:52 AM when queried, the specimen processing personnel was unable to provide the surveyor the twice annual verification of accuracy of Mohs' tissue slide examination and the Michigan Dermatological Society examination. 4. During the interview on November 14, 2018 at 9:52 AM, the specimen processing personnel confirmed the twice a year verification of accuracy was not performed and documented.</p>