

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b> 30D2170918	<b>(X3) Date Survey Completed</b> 01/11/2022
<b>Name of Provider or Supplier</b> Convenientmd Urgent Care - Littleton	<b>Street Address, City, State</b> 551 Meadow St, Littleton, NH	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6053</b>	<p><b>TECHNICAL CONSULTANT RESPONSIBILITIES</b> CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least semiannually during the first year the individual tests patient specimens.</p> <p>This STANDARD is not met as evidenced by: Based on record review and staff interview, the Technical Consultant (TC) failed to perform competency assessments semiannually within the first year for 2 new testing personnel performing hematology testing in 2020 and 2021. Findings include: 1) Review of personnel records revealed 5 new testing personnel hired in 2020 and 2021. Further review revealed 2 (TP1 &amp; TP2) out of the 5 new testing personnel have been performing complete blood count (CBC) testing for more than 1 year. There was no record of semiannual competency assessments in the first year of testing for TP1 (trained 8/2020) or TP2 (trained 5/2020). 2) Interview on 1/11/2022 at 10:15 a.m. with the practice manager and the TC revealed semiannual competency assessments had not been performed for TP1 and TP2.</p>