

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D0989114	(X3) Date Survey Completed 01/30/2019
Name of Provider or Supplier Allied Physicians Group Pllc	Street Address, City, State 100 Manetto Hill Road Ste 302, Plainview, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6018	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1407(e)(4)(iii)</p> <p>The laboratory director is responsible for the overall operation and administration of the laboratory, including the employment of personnel who are competent to perform test procedures, and record and report test results promptly, accurate, and proficiently and for assuring compliance with the applicable regulations. (e) The laboratory director must-- (e)(4)(iii) Ensure that all proficiency testing reports received are reviewed by the appropriate staff to evaluate the laboratory's performance and to identify any problems that require corrective action;</p> <p>This STANDARD is not met as evidenced by: Based on the surveyor's review of American Proficiency Institute (API) proficiency testing reports and an interview with the technical consultant and the testing personnel, the laboratory director failed to review (sign and date) the scored proficiency testing reports received from API to evaluate the laboratory's performance in calendar year 2017.</p>