

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D2043167	(X3) Date Survey Completed 08/14/2018
Name of Provider or Supplier Advanced Dermatology Pc	Street Address, City, State 449 North State Road Ste 203, Briarcliff Manor, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5413	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(b)</p> <p>The laboratory must define criteria for those conditions that are essential for proper storage of reagents and specimens, accurate and reliable test system operation, and test result reporting. The criteria must be consistent with the manufacturer's instructions, if provided. These conditions must be monitored and documented and, if applicable, include the following: (1) Water quality. (2) Temperature. (3) Humidity. (4) Protection of equipment and instruments from fluctuations and interruptions in electrical current that adversely affect patient test results and test reports.</p> <p>This STANDARD is not met as evidenced by: Based on a lack of humidity records and an interview with the practice manager, the laboratory failed to follow the manufacturer's instructions to monitor and document the room humidity where testing is performed. Findings Include: It was confirmed by the Moh's technician, on August 14, 2018, approximately 1:00 pm that the Moh's technician failed to follow the manufacturer's written criteria to monitor and document the humidity of the room where Moh's testing is performed from August 9, 2016 through the date of this survey.</p>
D6094	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(5)</p> <p>The laboratory director must ensure that the quality assessment programs are established and maintained to assure the quality of laboratory services provided and to identify failures in quality as they occur.</p> <p>This STANDARD is not met as evidenced by: Based on a review of procedures and an interview with the practice manager, the</p>

laboratory director failed to ensure that the laboratory's QA program was maintained as part of the laboratory's overall quality systems program. Refer to D5413