

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  34D2130391	<b>(X3) Date Survey Completed</b>  11/14/2023
<b>Name of Provider or Supplier</b>  Comprehensive Pain Consultants Of	<b>Street Address, City, State</b>  310 Overlook Road, Suite B, Asheville, NC	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5467</b>	<p><b>CONTROL PROCEDURES</b> CFR(s): 493.1256(d)(9)(g)</p> <p>Unless CMS Approves a procedure, specified in Appendix C of the State Operations Manual (CMS Pub. 7), that provides equivalent quality testing, the laboratory must-- When using calibration material as a control material, use calibration material from a different lot number than that used to establish a cut-off value or to calibrate the test system. (g) The laboratory must document all control procedures performed.</p> <p>This STANDARD is not met as evidenced by: Based upon interviews with TP (Testing Personnel) #1 and the LD (Lab Director) on 11/14/23, the laboratory failed to prepare LC/MS (liquid chromatography/mass spectrometry) quality control and calibration reagents from different standard stock solutions. Findings: During interview with TP#1 at approximately 9:20 a.m., the TP stated that both quality control and calibration reagents are prepared from the same single preparation of standard stock solution. The LD confirmed this practice during a summation interview at approximately 12:15 p.m.</p>