

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 36D2111882	(X3) Date Survey Completed 02/13/2023
Name of Provider or Supplier Oakview Dermatology	Street Address, City, State 2405 N Columbus St, Ste 100, Lancaster, OH	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6106	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(14)</p> <p>The laboratory director must ensure that an approved procedure manual is available to all personnel responsible for any aspect of the testing process.</p> <p>This STANDARD is not met as evidenced by: Based on review of the laboratory's policy and procedure manual and an interview with the Practice Manager (PM), the current Laboratory Director failed to ensure approved policies and procedures were available to all personnel responsible for any aspect of the testing process. This deficient practice had the potential to affect 10 patients tested under the subspecialty of Histopathology from 10/21/2022 through 01/01/2023. Findings Include: 1. Review of the CMS116 submitted for a change of Laboratory Director revealed a new Laboratory Director as of 10/21/2022. 2. Review of the laboratory's policy and procedure manual titled, "Oakview Dermatology, Mohs Laboratory", found the current Laboratory Director signature dated 01/02/2023. 3 The inspector requested policies and procedures approved by the current Laboratory Director from the PM. The PM confirmed the policies and procedures were not approved and signed by the current Laboratory Director until 01/02/2023. The interview occurred on 02/13/2023 at 10:10 AM.</p>