

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 37D0670187	(X3) Date Survey Completed 11/20/2025
Name of Provider or Supplier Csl Plasma, Inc	Street Address, City, State 5030 E Admiral Place, Tulsa, OK	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The recertification survey was performed on 11/20/2025. The laboratory was found in compliance with standard-level deficiencies cited.
D5775	<p>COMPARISON OF TEST RESULTS CFR(s): 493.1281(a)(c)</p> <p>(a) If a laboratory performs the same test using different methodologies or instruments, or performs the same test at multiple testing sites, the laboratory must have a system that twice a year evaluates and defines the relationship between test results using the different methodologies, instruments, or testing sites.</p> <p>This STANDARD is not met as evidenced by: Based on a review of records and interview with the Assistant Manager of Quality and Center Manager, the laboratory failed to have a system that evaluated and defined the relationship between six of six Reichert TS handheld refractometers at least twice a year during the review period of March 2024 through the current date. Findings include: (1) On 11/20/2025 at 09:42 am, the Center Manager stated the laboratory performed serum total protein testing using 6 digital, handheld Reichert TS meters (refractometers); (2) A review of records for the testing from March 2024 through the current date identified no evidence the relationship between the six analyzers had been evaluated as follows: (a) Prior to 07/02/2024 (b) Between 07/02/2024 and 11/20/2025 (3) The records were reviewed with the Assistant Manager of Quality and Center Manager, who stated on 11/20/2025 at 12:20 pm, there was no documentation to prove the relationship between the analyzers had been evaluated at least twice a year in 2024.</p>