

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b> 38D2023624	<b>(X3) Date Survey Completed</b> 05/20/2019
<b>Name of Provider or Supplier</b> Corvallis Medical Group	<b>Street Address, City, State</b> 800 Ne Circle Blvd, Corvallis, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6120</b>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(7)(8)</p> <p>(7) The technical supervisor is responsible for identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on review of testing personnel (TP) competency assessment documentation and discussion with the Laboratory Director (LD) who is also the Technical Supervisor (TS), the TS failed to ensure TP had all six (6) competency assessments performed during annual competency. Findings include: 1. Review of the competency assessment documents lacked assessment of problem solving skills. 2. Interview with the LD/TS on 5/20/2019 at approximately 12:00 pm confirmed he had neglected to assess this skill for TP.</p>
<b>D6126</b>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(8)(vi)</p> <p>The procedures for evaluation of the competency of the staff must include, but are not limited to assessment of problem solving skills.</p> <p>This STANDARD is not met as evidenced by: No deficiency details available.</p>