

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 38D2195111	(X3) Date Survey Completed 08/10/2021
Name of Provider or Supplier Rackleff Place	Street Address, City, State 655 Sw 13th Ave, Canby, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D1002	<p>REPORTING OF SARS-CoV-2 TEST RESULTS</p> <p>During the Public Health Emergency, as defined in 400.200 of this chapter, each laboratory that performs a test that is intended to detect SARS-CoV-2 or to diagnose a possible case of COVID-19 (hereinafter referred to as a "SARS-CoV-2 test") must report SARS-CoV-2 test results to the Secretary in such form and manner, and at such timing and frequency, as the Secretary may prescribe.</p> <p>This CONDITION is not met as evidenced by: Review of records and discussion with the Facility Administrator failed to report all SARS CoV-2 results to the Oregon Health Authority (OHA). Finding includes 1. Review of records revealed the laboratory started performing SARS CoV-2 testing using the Abbott BinaxNow Rapid Antigen Test cards on May 28, 2021 A total of 22 test results (all negative test results) from May 28, 2021 until August 2, 2021 were not reported to OHA . 2. The Facility Administrator of Rackleff Place confirmed that they were not reporting COVID test results to Oregon Health Authority on August 10, 2021 at 0845 am by virtual interview.</p>