

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D0179820	(X3) Date Survey Completed 02/16/2022
Name of Provider or Supplier Cornerstone Care Ped Ctr Of Washington	Street Address, City, State 351 West Beau St, Ste 200, Washington, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on lack of competency assessment (CA) records and interview with the Medical Assistant (MA), the Technical Consultant (TC) failed to assess the competency of 2 of 3 Testing Personnel (TP) who performed throat culture examinations in 2020. Finding Include: 1. On the day of survey, 2/16/2022 at 11:46 a. m., The MA could not provide CA records for 2 of 3 (CMS 209 Personnel #2 and #3) who performed throat culture examinations from 1/1/2020 to 12/31/2020 2. The laboratory performed 47 throat cultures annually. 3. The MA confirmed the findings above on 2/16/2022 at 02:00 p.m.</p>