

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D0189583	(X3) Date Survey Completed 10/18/2018
Name of Provider or Supplier Pottsville Cancer Clinic	Street Address, City, State 700 Schuylkill Manor Road Suite 7, Pottsville, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6051	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)(v)</p> <p>The procedures for evaluation of the competency of the staff must include, but are not limited to assessment of test performance through testing previously analyzed specimens, internal blind testing samples or external proficiency testing samples.</p> <p>This STANDARD is not met as evidenced by: Based on, the review of personnel competency assessment records, American Proficiency Institute (API) proficiency testing (PT) records and interview with testing personnel (TP) #1, the Technical Consultant failed to assess the competency of 3 of 4 TP through internal blind testing samples or external PT samples for Complete Blood Count (CBC) from 2017 to the date of survey. Findings Include: 1. On the day of survey, 10/18/2018, review of competency assessment records revealed the laboratory did not assess the test performance of 3 of 4 TP through internal blind testing samples or external PT samples for: - API CBC PT events #2 and #3 in 2017. - API CBC PT events #1 and #2 in 2018. 2. TP #1 was the only personnel performing yearly PT evaluations. 3. TP#1 confirmed the findings above on 10/18/2018 around 10:20 am.</p>