

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D0195109	(X3) Date Survey Completed 06/15/2018
Name of Provider or Supplier Bryn Mawr Skin And Cancer Institute	Street Address, City, State 919 Conestoga Road Suite 106 Bldg 2, Bryn Mawr, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5601	<p>HISTOPATHOLOGY CFR(s): 493.1273(a)(f)</p> <p>(a) As specified in 493.1256(e)(3), fluorescent and immunohistochemical stains must be checked for positive and negative reactivity each time of use. For all other differential or special stains, a control slide of known reactivity must be stained with each patient slide or group of patient slides. Reactions of the control slide with each special stain must be documented. (f) The laboratory must document all control procedures performed, as specified in this section.</p> <p>This STANDARD is not met as evidenced by: Based on review of Laboratory Quality Control records and interview with the Mohs Technician and the Practice Operations Manager, the Laboratory failed to document all quality control procedures performed from 01/01/2017 and the date of the survey (06/15/2018). Findings include: 1. Quality Control records for Immuno Histo Chemistry and Periodic Acid Schiff slides read between 2017 and 2018 were not found.during the survey. 2. During the survey, the Practice Operations Mananager confirmed the above finding.</p>