

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D0942535	(X3) Date Survey Completed 08/06/2019
Name of Provider or Supplier Chester County Rheumatology Pc	Street Address, City, State 795 E Marshall Street Ste 101, West Chester, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6128	<p>TECHNICAL SUPERVISOR RESPONSIBILITIES CFR(s): 493.1451(b)(9)</p> <p>The technical supervisor is responsible for evaluating and documenting the performance of individuals responsible for high complexity testing at least annually after the first year, unless test methodology or instrumentation changes, in which case, prior to reporting patient test results, the individual's performance must be reevaluated to include the use of the new test methodology or instrumentation.</p> <p>This STANDARD is not met as evidenced by: By review of the personnel record and personnel interview of the Practice Manager, at the time of inspection (10:00/06/2019), the Technical Supervisor failed to document the performance of all testing personnel annually for , (12/01/2017 through (08/06 /2019). Findings include: 1.. Review of the personnel record revealed no documentation of annual competency for 1 of 2 Testing Personnel from (12/01/2017 through (08/06/2019). 2. During the survey (10:45 08/06/2019), the Practice Manager confirmed the above finding.</p>