

| | | |
|--|--|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 39D0969431 | (X3) Date Survey Completed 07/18/2019 |
| Name of Provider or Supplier Grove City Hospital Outpatient Services | Street Address, City, State 3124 Wilmington Road, New Castle, PA | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|---|
| D6054 | <p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(9)</p> <p>The technical consultant is responsible for evaluating and documenting the performance of individuals responsible for moderate complexity testing at least annually, after the first year.</p> <p>This STANDARD is not met as evidenced by: By review of the competency records and personnel interview of the Testing Personnel and Technical Consultant, on (07/18/2019), the Technical Consultant failed to document Testing Personnel competency at least annually for one of two years, (01/10/2018 through 01/10/2019). Findings include: 1. The Testing Personnel competency was last documented 01/10/2018. 2. During the survey (14:00 07/18/2019) the Technical Consultant confirmed that no Testing Personnel competency assessment was performed in 2019.</p> |