

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  39D2149361	<b>(X3) Date Survey Completed</b>  08/26/2022
<b>Name of Provider or Supplier</b>  Center For Interventional Pain & Spine Llc	<b>Street Address, City, State</b>  300 Welsh Road, Building 2, Suite 104, Horsham, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6125</b>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(8)(v)</p> <p>The procedures for evaluation of the competency of the staff must include, but are not limited to assessment of test performance through testing previously analyzed specimens, internal blind testing samples or external proficiency testing samples.</p> <p>This STANDARD is not met as evidenced by: Based on review of the Training and Competency Assessment form records and interview with the Technical Supervisor (TS), General Supervisor (GS), and Laboratory Director (LD), the TS failed to assess test performance through testing previously analyzed specimens, internal blind testing samples or external proficiency testing samples for 1 of 5 Testing Personnel (TP) who performed toxicology screening and confirmatory test from 04/26/2021 to 08/26/2022. Findings include: 1. On the day of inspection, 08/26/2022 at 09:33 AM, a review of competency assessment records revealed that the TS did not perform an assessment on TP #4 on external proficiency testing samples or through internal blind testing samples who performed toxicology screening and confirmatory test from 4/26/2021 through 08/26/2022. 2. Technical Supervisor (TS), General Supervisor (GS), and Laboratory Director (LD) confirmed the above findings on 08/26/2022 at 11:48 AM.</p>