

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 42D0253791	(X3) Date Survey Completed 08/27/2024
Name of Provider or Supplier Allendale County Hospital	Street Address, City, State 1787 Allendale-Fairfax Highway, Fairfax, SC	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An onsite announced CLIA recertification survey was conducted on August 27, 2024 at Allendale County Hospital's clinical laboratory by the South Carolina Department of Public Health's (SC DPH) Bureau of Nursing Homes and Medical Services. The laboratory was found to be out of compliance with 42 CFR Part 493, CLIA Requirements for Laboratories. The following is a description of Condition and Standard level deficiencies cited:
D6000	<p>MODERATE COMPLEXITY LABORATORY DIRECTOR CFR(s): 493.1403</p> <p>The laboratory must have a director who meets the qualification requirements of 493.1405 of this subpart and provides overall management and direction in accordance with 493.1407 of this subpart.</p> <p>This CONDITION is not met as evidenced by: Based on a review of the CMS 209 personnel form and interview with testing personnel # 1 and Chief Executive Officer (CEO), it was determined that the laboratory failed to have a qualified laboratory director for moderate complexity testing for five of five months. Findings included: 1. On 10/07/2024, a review of the CMS 209 personnel form revealed the laboratory failed to have a qualified laboratory director for moderate complexity testing for five of five months.</p>