

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 42D0682447	(X3) Date Survey Completed 02/28/2022
Name of Provider or Supplier Trident Dermatology	Street Address, City, State 9295 Medical Plaza Drive, Suite A, North Charleston, SC	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2016	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: During the onsite recertification survey on 02/28/2022, based on review of CASPER report 155D and graded reports from American Proficiency Institute (API), it was determined that the laboratory failed to successfully participate in proficiency testing for the specialty of mycology, the analyte dermatophyte identification for two of three consecutive proficiency testing events reviewed (2020, Event 3 and 2021, Event 2). See D2038 and D2046.</p>
D2038	MYCOLOGY

CFR(s): 493.827(a)

Failure to attain an overall testing event score of at least 80 percent is unsatisfactory performance.

This STANDARD is not met as evidenced by:

During an onsite recertification survey performed on 02/28/2022, based on review of the CASPER report 155D and laboratory proficiency testing records (graded copies from API), it was determined that the laboratory failed to attain a score of at least 80 percent in proficiency testing for the specialty of mycology, the analyte dermatophyte identification for two of three consecutive proficiency testing events (2020, Event 3 and 2021, Event 2). The findings include: 1. Review of CASPER report 155D revealed the following dermatophyte identification proficiency scores for your laboratory: a. 2020, Event 3: 0% b. 2021, Event 2: 60% 2. The scores were confirmed upon review of the graded API results. Scores less than 80% for these analytes indicate failure or unsatisfactory performance. A failure of the analytes for two consecutive or two out of three testing events is scored as unsuccessful. A failure of the analyte for three consecutive or three out of four/five events is scored as a repeat unsuccessful.

D2046

MYCOLOGY

CFR(s): 493.827(e)

Failure to achieve an overall testing event score of satisfactory performance for two consecutive testing events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

During an onsite recertification survey performed on 02/28/2022, based on review of CASPER report 155D and graded API results, it was determined that the laboratory failed to achieve satisfactory performance for the analyte dermatophyte identification in two of three consecutive testing events (2020, Event 3 and 2021, Event 2) resulting in unsuccessful proficiency testing performance. See D2038.