

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D0312501	(X3) Date Survey Completed 05/23/2024
Name of Provider or Supplier Anne Arundel Dermatology, Pa	Street Address, City, State 1450 N Dowell Springs Blvd, Suite 210, Knoxville, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5473	<p>CONTROL PROCEDURES CFR(s): 493.1256(e)(2)(g)</p> <p>(e) For reagent, media, and supply checks, the laboratory must do the following: (e) (2) Each day of use (unless otherwise specified in this subpart), test staining materials for intended reactivity to ensure predictable staining characteristics. Control materials for both positive and negative reactivity must be included, as appropriate. (g) The laboratory must document all control procedures performed.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the laboratory's Hematoxylin and Eosin (H&E) stain control slide log, laboratory procedure, and staff interview, the laboratory failed to define the predicted characteristics of the H&E stain in 2023 through the survey date (05.23.2024). The findings include: 1. A review of the laboratory's H&E stain control slide logs revealed no documentation of the predicted characteristics of the H&E stain quality for 2023 through the survey date of 05.23.2024. 2. A review of the laboratory's "MOHS PATIENT & SLIDE NUMBERING SYSTEM" procedure revealed that it did not define predictable characteristics of the H&E stain quality. 3. During an interview on 05.23.2024 at 9:30 a.m., the lead histotechnician confirmed the laboratory had not defined or documented the predicted characteristics of the H&E stain quality for 2023 through the survey date of 05.23.2024.</p>