

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D0710014	(X3) Date Survey Completed 05/12/2020
Name of Provider or Supplier Bmg Family Physicians Group Foundation, Inc	Street Address, City, State 7685 Winchester Rd, Suite 100, Memphis, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D2016	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: The laboratory failed to maintain satisfactory participation for two consecutive proficiency testing (PT) events for the red blood cell (RBC) analyte, resulting in the first unsuccessful PT occurrence for the RBC analyte. (Refer to D2130)</p>
D2130	<p>HEMATOLOGY CFR(s): 493.851(f)</p> <p>Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.</p>

This STANDARD is not met as evidenced by:

Based on a desk review of the Centers for Medicare and Medicaid Services Casper Report 155 (CMS 155) and the laboratory's 2019 and 2020 proficiency testing (PT) records, the laboratory failed to maintain satisfactory performance for the red blood cell (RBC) analyte in two consecutive PT events, resulting in the first unsuccessful PT occurrence for the RBC analyte. The findings include: 1) Review of the CMS 155 revealed the following unsatisfactory PT scores for the RBC analyte: 2019 event three: 60% 2020 event one: 0% 2) Review of the laboratory's proficiency testing records revealed the following: 2019 event three: Sample numbers SXT-11 and SXT-12 scored as "Fail," resulting in an overall score of 60% for the RBC analyte. 2020 event one: Sample numbers SXT-1, SXT-2, SXT-3, SXT-4, SXT-5 scored as "Fail-No Results Received," resulting in an overall score of 0% for the RBC analyte, and the first unsuccessful PT occurrence for the RBC analyte.