

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D1019539	(X3) Date Survey Completed 05/16/2025
Name of Provider or Supplier Brentwood Dermatology	Street Address, City, State 343 Franklin Road, Suite 202, Brentwood, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5217	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on a review of laboratory policy, split-sample testing logs, and staff interview, the laboratory failed to perform twice-yearly verification of accuracy for KOH fungal testing and scabies testing for three of three testing personnel (TP) in 2023 and 2024. The findings include: 1. A review of the Provider Performed Microscopy (PPM) Lab Manual revealed the following requirements: - "To evaluate and demonstrate proficiency, at least twice per year, split-sample testing is performed on at least two specimens for each test performed." - "Proficiency testing/split-sample testing duties will be rotated among all personnel who examine patient samples for PPM." 2. A review of the PPM Split-Sample Testing Log/Quality Assurance revealed that one of three TP in 2023 and three of three TP in 2024 failed to perform the twice-yearly testing. 3. An interview with the histology technician and the clinic manager on 05/16/2025 at 11:30 a.m. confirmed the findings.</p>