

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  46D2138257	<b>(X3) Date Survey Completed</b>  01/14/2026
<b>Name of Provider or Supplier</b>  Revere Health Salem Dermatology	<b>Street Address, City, State</b>  555 West Sr-164 Winter Hallway, Salem, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D6120</b>	<p><b>TECHNICAL SUPERVISOR RESPONSIBILITIES</b> CFR(s): 493.1451(b)(7)(8)</p> <p>(b)(7) Identifying training needs and assuring that each individual performing tests receives regular in-service training and education appropriate for the type and complexity of the laboratory services performed; (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on lack of competency documentation and interview with the Office Manager, the laboratory failed to evaluate competency for KOH testing for 1 out of 1 Testing Personnel (TP) . Findings include: 1. A laboratory record review revealed lack of competency documentation for KOH testing since the last survey on 4/18/2024 for 1 out of 1 TP. 2. Interview with Office Manager on 1/14/2026 at approximately 12:13 p. m. confirmed that the laboratory failed to document competency for KOH testing for 1 out of 1 TP.</p>