

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D2161455	(X3) Date Survey Completed 08/11/2021
Name of Provider or Supplier Revere Health Spanish Fork Urgent Care	Street Address, City, State 972 North 600 East, Spanish Fork, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5785	<p>CORRECTIVE ACTIONS CFR(s): 493.1282(b)(3)</p> <p>(b) The laboratory must document all corrective actions taken, including actions taken when any of the following occur: (b)(3) The criteria for proper storage of reagents and specimens, as specified under 493.1252(b), are not met.</p> <p>This STANDARD is not met as evidenced by: Based on document review and interview with Technical Consultant, corrective action for out of temperature range reagent freezer was not documented for 29 instances of out of range temperature readings for the time period of January 2021 through June 2021. The laboratory performs approximately 628 CBC tests annually. Findings include: 1. Reagent freezer temperature log included 29 dates of recorded temperature above acceptable range from January 2021 through June 2021. 2. No corrective action was noted on temperature logs for out of range temperatures. 3. In an interview on 8 /11/21 at approximately 3:00 pm, the technical consultant confirmed that corrective action was not documented for out of range freezer temperatures.</p>