

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  46D2167500	<b>(X3) Date Survey Completed</b>  08/29/2022
<b>Name of Provider or Supplier</b>  Revere Health Provo Family Medicine/Urgent Care	<b>Street Address, City, State</b>  1055 N 500 W Building A, Provo, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5209</b>	<p><b>PERSONNEL COMPETENCY ASSESSMENT POLICIES</b> CFR(s): 493.1235</p> <p>As specified in the personnel requirements in subpart M, the laboratory must establish and follow written policies and procedures to assess employee and, if applicable, consultant competency.</p> <p>This STANDARD is not met as evidenced by: Based on a review of competency assessment documentation, policies and procedures, and an interview with the Technical Consultant staff, the laboratory failed to establish and follow written policies to assess competency for 5 of 5 Technical Consultants (TC) for the years 2020 and 2021. Findings include: 1. A review of competency assessment documentation at approximately 12:15pm on 8/29/22, revealed that the laboratory failed to document competency assessments for 5 of 5 TCs during 2020 and 2021. 2. A review of the laboratory's policies and procedures at approximately 12:30pm on 8/29/22, revealed that the laboratory had failed to establish policies and procedures to assess TC competency. 3. In an interview with TC2 at approximately 12:35pm on 8/29/22, it was confirmed that the laboratory had failed to establish policies and procedures to assess TC competency.</p>