

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D2183345	(X3) Date Survey Completed 04/12/2021
Name of Provider or Supplier Progenitor Mdx Inc	Street Address, City, State 675 Arapeen Suite 103b, Salt Lake City, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5785	<p>CORRECTIVE ACTIONS CFR(s): 493.1282(b)(3)</p> <p>(b) The laboratory must document all corrective actions taken, including actions taken when any of the following occur: (b)(3) The criteria for proper storage of reagents and specimens, as specified under 493.1252(b), are not met.</p> <p>This STANDARD is not met as evidenced by: Based on document review and interview, corrective action was not taken or documented for Sample Fridge temperature being out of acceptable range. Findings include: 1. Sample fridge acceptable range is listed as 2-8C. 2. Sample fridge recorded temperature was 1C for 32 days during the months of July 2020 through February 2021. 3. No corrective action is noted on any temperature logs during these months. 4. In an interview on 4/12/2021 at approximately 1:30 pm, the Laboratory Director and General Supervisor confirmed that the Sample Fridge temperature was out of range and corrective action was not taken.</p>