

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 46D2257034	(X3) Date Survey Completed 07/10/2024
Name of Provider or Supplier Rocky Mountain Laboratories	Street Address, City, State 12217 Lone Peak Pkwy, Ste 100, Draper, UT	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A CLIA complaint survey conducted on 07/10/2025, found the Rocky Mountain Laboratories laboratory located in Draper, Utah to be in substantial compliance with 42 CFR, Part 493; The Clinical Laboratory Improvement Amendments. The surveyor cited no deficiencies, and the laboratory has been recommended for recertification.