

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 49D2276616	(X3) Date Survey Completed 10/26/2023
Name of Provider or Supplier Map Rc Llc DbA Prime Regenerative And	Street Address, City, State 2565 Cowan Blvd, Fredericksburg, VA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An announced CLIA initial survey was conducted at MAP RC LLC dba Prime Regenerative & Pain Management on October 25-26, 2023 by the Virginia Department of Health's Office of Licensure and Certification. The laboratory was surveyed under 42 CFR part 493 CLIA Regulations. The specific deficiency cited is as follows:
D5805	<p>TEST REPORT CFR(s): 493.1291(c)</p> <p>The test report must indicate the following: (c)(1) For positive patient identification, either the patient's name and identification number, or a unique patient identifier and identification number. (c)(2) The name and address of the laboratory location where the test was performed. (c)(3) The test report date. (c)(4) The test performed. (c)(5) Specimen source, when appropriate. (c)(6) The test result and, if applicable, the units of measurement or interpretation, or both. (c)(7) Any information regarding the condition and disposition of specimens that do not meet the laboratory's criteria for acceptability.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the facility's Centers for Medicare and Medicaid Services Application for Certification (CMS 116) form, patient reports, and interviews, the laboratory failed to correctly identify their address as the performing laboratory for three (3) of 3 randomly selected patient's urine drug test reports as reviewed on October 25, 2023. The findings include: 1. Review of the laboratory's CMS 116 form revealed a laboratory name and facility physical location address as: MAP RC LLC dba Prime Regenerative & Pain Management 2565 Cowan Blvd. Fredericksburg, VA 2. Review of 3 randomly selected patient reports (accession numbers UR23-0656, UR23-0265, and UR23-0450) revealed the testing location listed as: Prime Regenerative and Pain Management 402 Chatham Square Office Park Fredericksburg, VA 22405 In an interview with the Quality Technical Supervisor on October 25,</p>

2023, at approximately 11:00 AM, the Quality Technical Supervisor stated, "I didn't know the address was incorrect. I will have the address corrected now." 3. In an exit interview with the Quality Technical Supervisor and Technical Supervisor on October 26, 2023 at approximately 11:15 AM, the above findings were confirmed.