

|  |  |   |
|--|--|---|
| <b>Statement of Deficiencies</b>   | <b>(X1) Provider/Supplier/CLIA Identification Number</b><br>51D2151883       | <b>(X3) Date Survey Completed</b><br>06/06/2023 |
| <b>Name of Provider or Supplier</b><br>Chesapeake Healthcare Center, Llc   | <b>Street Address, City, State</b><br>11950 Maccorkle Avenue, Charleston, WV |   |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. |  |   |

| <b>(X4) ID Prefix Tag</b> | <b>Summary Statement of Deficiencies</b>  |
|---------------------------|---|
| <b>D0000</b>              | An announced, on site, routine recertification survey was conducted at Chesapeake Healthcare Center on June 6, 2023, by the West Virginia Office of Laboratory Services. The laboratory was surveyed to assess compliance with the Federal Clinical Laboratory Improvement Amendment (CLIA) regulations under 42 CFR 493. Specific deficiencies cited are explained below.  |
| <b>D6064</b>              | <p><b>TESTING PERSONNEL QUALIFICATIONS</b><br/>CFR(s): 493.1423(a)</p> <p>Each individual performing moderate complexity testing must possess a current license issued by the State in which the laboratory is located, if such licensing is required.</p> <p>This STANDARD is not met as evidenced by:<br/>Based on review of personnel files, primary source verification, and interview one of two laboratory testing personnel (TP1) performing moderate complexity testing failed to possess a current West Virginia laboratory license as required by the West Virginia 64 CSR 57 Clinical Laboratory Practitioner Licensure and Certification. Findings: 1. A review of testing personnel records and the WV licensure primary source verification portal identified that one of two laboratory testing personnel (TP1) had an expired laboratory license at the time of survey (expired 5/1/23). 2. An interview with the laboratory manager, 6/6/23 at approximately 9:45, confirmed the findings.</p> |