

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  52D0686802	<b>(X3) Date Survey Completed</b>  08/21/2019
<b>Name of Provider or Supplier</b>  Vibrant Health Family Clinics-Ellsworth	<b>Street Address, City, State</b>  144 S Plum St, Ellsworth, WI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D2016</b>	<p>SUCCESSFUL PARTICIPATION CFR(s): 493.803(a)(b)(c)</p> <p>(a) Each laboratory performing nonwaived testing must successfully participate in a proficiency testing program approved by CMS, if applicable, as described in subpart I of this part for each specialty, subspecialty, and analyte or test in which the laboratory is certified under CLIA. (b) Except as specified in paragraph (c) of this section, if a laboratory fails to participate successfully in proficiency testing for a given specialty, subspecialty, analyte or test, as defined in this section, or fails to take remedial action when an individual fails gynecologic cytology, CMS imposes sanctions, as specified in subpart R of this part. (c) If a laboratory fails to perform successfully in a CMS-approved proficiency testing program, for the initial unsuccessful performance, CMS may direct the laboratory to undertake training of its personnel or to obtain technical assistance, or both, rather than imposing alternative or principle sanctions except when one or more of the following conditions exists: (1) There is immediate jeopardy to patient health and safety. (2) The laboratory fails to provide CMS or a CMS agent with satisfactory evidence that it has taken steps to correct the problem identified by the unsuccessful proficiency testing performance. (3) The laboratory has a poor compliance history.</p> <p>This CONDITION is not met as evidenced by: Based on surveyor review of the federal Certification and Survey Provider Enhanced Reports (CASPER) Proficiency Testing (PT) and Wisconsin State Laboratory of Hygiene (WSLH) Proficiency Testing (PT) records, the laboratory failed to successfully participate in PT for the Hematocrit analyte in the Specialty of Hematology for events 2019-1 and 2019-2. See D2130.</p>
<b>D2130</b>	<p>HEMATOLOGY CFR(s): 493.851(f)</p>

Failure to achieve satisfactory performance for the same analyte in two consecutive events or two out of three consecutive testing events is unsuccessful performance.

This STANDARD is not met as evidenced by:

Based on surveyor review of the federal Certification and Survey Provider Enhanced Reports (CASPER) Proficiency Testing (PT) and Wisconsin State Laboratory of Hygiene (WSLH) PT records, the laboratory failed to achieve satisfactory performance in PT for the Hematocrit analyte in the Specialty of Hematology for events 2019-1 and 2019-2. Findings include: 1. Review of PT records in the federal CASPER reporting system shows that the laboratory failed two consecutive PT events for the Hematocrit analyte in the Specialty of Hematology- Event 2019-1, score 40% and Event 2019-2, score 0%. 2. Surveyor review of the WSLH PT evaluation reports on August 21, 2019 confirmed the failed 2019 PT scores for the Hematocrit analyte. This results in a failure to achieve an overall testing event score of satisfactory performance for two consecutive testing events which is unsuccessful PT performance.