

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  52D2250885	<b>(X3) Date Survey Completed</b>  04/11/2024
<b>Name of Provider or Supplier</b>  Tareen Dermatology	<b>Street Address, City, State</b>  7021 West Lowes Creek Road Suite A, Eau Claire, WI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5217</b>	<p>EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1)</p> <p>At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of laboratory records and interview with the laboratory director, the laboratory did not verify the accuracy of histology microscopic slide interpretation testing for two of two events in 2023. Findings include: 1. Review of laboratory records showed no evidence of twice annual accuracy checks of histology microscopic slide interpretation testing in 2023. 2. Interview with the laboratory director on April 11, 2024, at 9:40 AM confirmed the laboratory had not verified the accuracy of the test twice annually in 2023.</p>