

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D2067119	(X3) Date Survey Completed 11/17/2020
Name of Provider or Supplier Pathlab Inc	Street Address, City, State 4266 Industry Dr, Ste 1, Sierra Vista, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	In all areas reviewed the Laboratory was found to be in compliance with the requirements of 42 CFR Part 493, Requirements for Laboratory Services, on the day of the survey.