

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 03D2136692	(X3) Date Survey Completed 10/31/2018
Name of Provider or Supplier White Mountain Dermatology	Street Address, City, State 7303 E Main St, Ste 112, Mesa, AZ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5433	<p>MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(b)(1)</p> <p>For equipment, instruments, or test systems developed in-house, commercially available and modified by the laboratory, or maintenance and function check protocols are not provided by the manufacturer, the laboratory must establish a maintenance protocol that ensures equipment, instrument, and test system performance that is necessary for accurate and reliable test results and test result reporting. The laboratory must perform and document the maintenance activities specified in paragraph (b)(1)(i) of this section.</p> <p>This STANDARD is not met as evidenced by: Based on lack of maintenance policies for review and interview with the facility personnel, the laboratory failed to establish a microscope maintenance policy that indicates specific routine maintenance procedures as well as scheduled preventative maintenance procedures. Findings include: 1. The policy and procedure manual presented for review during the survey did not contain any policies with regards to microscope maintenance. 2. The facility personnel acknowledged that there was no microscope maintenance policy contained in the manual. 3. The laboratories annual test volume under the sub-specialty of Histopathology is 120.</p>