

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  05D1075041	<b>(X3) Date Survey Completed</b>  11/09/2020
<b>Name of Provider or Supplier</b>  Center For Advanced Dermatology, Inc	<b>Street Address, City, State</b>  301 W Huntington Dr Ste 215, Arcadia, CA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D5429</b>	<p><b>MAINTENANCE AND FUNCTION CHECKS</b> CFR(s): 493.1254(a)(1)</p> <p>For unmodified manufacturer's equipment, instruments, or test systems, the laboratory must perform and document maintenance as defined by the manufacturer and with at least the frequency specified by the manufacturer.</p> <p>This STANDARD is not met as evidenced by: Based on the laboratory's procedure manual, lack of documentation, and interview with the laboratory director (LD), it was determined that the laboratory failed to perform and document maintenance and calibration as defined by the manufacturer and with at least the frequency specified by the manufacturer for the laboratory equipment. The findings included: 1. The laboratory's standard operating procedure (SOP) indicates that annual maintenance and calibration by a contracted equipment service according to manufacturer's requirements be performed on the WESCO microscope. 2. The LD confirmed 11/09/2020 at approximately 11:00 a.m. that the laboratory failed to follow SOP for maintenance and calibration of the microscope. 3. According to the annual test volume declared by the laboratory on 11/09/2020; the laboratory performs approximately 440 test annually.</p>