

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 06D0901071	(X3) Date Survey Completed 05/20/2021
Name of Provider or Supplier Centrum Surgery Center	Street Address, City, State 8200 E Belleview Ave, Ste 300e, Greenwood Village, CO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	Based on an on-site recertification survey conducted on 05-20-2021, the Centrum Surgery Center laboratory located in Greenwood Village, Colorado was found to be in substantial compliance with the conditions of participation in 42 CFR, Part 493; The Clinical Laboratory Improvement Amendments. No deficiencies were cited, and the laboratory is recommended for recertification.