

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 06D2149944	(X3) Date Survey Completed 04/19/2019
Name of Provider or Supplier Bella Derma, Llc	Street Address, City, State 919 Grand Ave, Glenwood Springs, CO	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5401	<p>PROCEDURE MANUAL CFR(s): 493.1251(a)</p> <p>A written procedures manual for all tests, assays, and examinations performed by the laboratory must be available to, and followed by, laboratory personnel. Textbooks may supplement but not replace the laboratory's written procedures for testing or examining specimens.</p> <p>This STANDARD is not met as evidenced by: Based on a review of the procedure manual and staff confirmation, the laboratory failed to provide during the onsite survey a written procedure for staff to follow for potassium hydroxide (KOH) examinations of skin, hair, and nails, reviewed and signed by the laboratory director since KOH testing began in December 2019.</p>