Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D0978532	(X3) Date Survey Completed 05/17/2022
Name of Provider or Supplier Skin & Cancer Associates Llp	**Street Address, City, State** 7800 Sw 87th Ave Ste 300c, Miami, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A recertification survey conducted on 05/17/2022 found the SKIN AND CANCER ASSOCIATES LLP clinical laboratory not in compliance with 42 CFR Part 493, Requirements for Laboratories.
D5217	EVALUATION OF PROFICIENCY TESTING PERFORMANCE CFR(s): 493.1236(c)(1) At least twice annually, the laboratory must verify the accuracy of any test or procedure it performs that is not included in subpart I of this part. This STANDARD is not met as evidenced by: Based on record review and staff interview, the laboratory failed to verify the accuracy of the reading and interpretation of the Hematoxylin and Eosin (H&E) stain at least twice annually in 2020. Findings include: -Review of laboratory peer review records revealed that the laboratory had no documentation for year 2020. -During an interview on 05/17/2022 at 11:30 A.M., the MOHS Consultant confirmed that the laboratory had no documentation of accuracy verification of the reading and interpretation of Hematoxylin and Eosin (H&E) stain at least twice annually in 2020.